



# WACO Great Lakes 2T-1A-2

## SERVICE INFORMATION LETTER

---

**NUMBER: GL-SIL003**

Issued: 31 Aug 2023

Revised: None.

---

**SUBJECT: Great Lakes Fuel System Inspection**

---

**EFFECTIVITY:** Great Lakes 2T-1A-2: All serial numbers.

**PURPOSE:** This service information letter reminds owners and operators to perform inspections on the fuel header tank for evidence of fuel seepage.

**REFERENCE:** 2T-1A-2 Maintenance Manual:

- For Serial Numbers 1200 and onward: in Sections 2.2.1 and 2.3.10 of the 2T-1A-2 Great Lakes by WACO Maintenance Manual WCGL13-AMM1
- For Serial Numbers prior to 1200: Section II Item 20 in the 100-hour inspection in the Model 2T-1A Maintenance and Rigging Manual.

**DISCUSSION:** Residual fuel was discovered during an annual inspection on a Great Lakes aircraft on the header tank located behind the forward instrument panel. A similar issue with a fuel fitting was found on a second header tank assembly.

**ACTION:** This Service Information Letter is to remind owners and operators to perform inspections on the fuel lines and fuel system with additional focus on fuel header tank fittings for evidence of seepage. This site is in close proximity to the front passenger and can often be overlooked due to its location behind the instrument panel.

References for the applicable inspections are provided above.